# PDR  RID  Report

| | | |
|---|---|---|
| **Originator** CHANG,ED | **Phone No** 286-6964 | **RID ID   PDR** 88 |
| **Organization** 421 | | **Review** FOS |
| **E Mail Address** edward.chang@gsfc.nasa.gov | | **Originator Ref** DR3 |
| **Document** FOS Requirements Spec | | **Priority** 2 |

**Section** 7.2.5.5          **Page** 7-28                **Figure Table** NA

---

**Category Name** Requirements                                    **Actionee** HAIS

**Sub Category**

**Subject** Automatic update of state checker

**Description of Problem or Suggestion:**

Commands issued in real-time which will affect the state of the spacecraft are not automatically incorporated into the expected state.

**Originator's Recommendation**

Add a requirements to automatically include the results of real- time commands into the expected state of the spacecraft.

---

**GSFC Response by:**                               **GSFC Response Date**

**HAIS Response by:**     D. Herring          **HAIS Schedule** 1/20/95

**HAIS R. E.**     D. Dunn          **HAIS Response Date** 1/18/95

Refer to PDR #42 RID response.

---

**Status**  **Closed**          **Date Closed** **2/1/95**          **Sponsor** **Johns**

****** Attachment if any ******

---